Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

February 2023

Items	Date	Status*	Follow up Action		
Water Quality					
The stagnant water is observed and they should pump immediately.	16 Feb 2023	✓	Item was rectified on 23 Feb 2023.		
Ecology					
Noise					
Landscape and Visual					
Air Quality					
The stockpile of dusty material were observed inside the tunnel, they should be removed when not in used.	9 Feb 2023	√	Item was rectified on 16 Feb 2023.		
The NRMM lable display on the machinery is unclear	23 Feb 2023	#	Follow up in the next reporting month.		
Waste / Chemical Management					
No drip tray is provided for the chemical / oil continaer.	26 Jan 2023	√	Item was rectified on 2 Mar 2023.		
Impact on Cultural Heritage					
Permits / Licenses					

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but improved by the contractor

MA20003/App F CINOTECH

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

March 2023

Items	Date	Status*	Follow up Action		
Water Quality					
Noise					
Landscape and Visual					
Air Quality					
The NRMM label display on the machinery is unclear.	23 Feb 2023	~	Item was rectified on 2 Mar 2023.		
The NRMM label display on the machinery is unclear.	2 Mar 2023	~	Item was rectified on 9 Mar 2023.		
The cement bag is not covered when not in used.	23 Mar 2023	/	Item was rectified on 30 Mar 2023.		
Waste / Chemical Management					
Oil leakage was observed on the floor near the entrance of tunnel.	23 Mar 2023	~	Item was rectified on 30 Mar 2023.		
No drip tray is provided for the chemical / oil container.	23 Mar 2023	~	Item was rectified on 30 Mar 2023.		
Impact on Cultural Heritage					
Permits / Licenses					

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but rectified by the contractor

MA20003/App F CINOTECH

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

April 2023

Items	Date	Status*	Follow up Action		
Water Quality					
Stagnant water was observed at the tunnel entrance.	6 Apr 2023	~	Item was rectified on 13 Apr 2023.		
Stagnant water was observed on the drip tray at the site entrance.	27 Apr 2023	#	Follow up in the next reporting month.		
Noise					
Landscape and Visual					
-					
Air Quality					
The NRMM label display on the machinery is unclear.	6 Apr 2023	~	Item was rectified on 13 Apr 2023.		
Waste / Chemical Management					
General refuses were found near the tunnel entrance.	6 Apr 2023	V	Item was rectified on 13 Apr 2023.		
Chemical wastes were observed in the tunnel area, contractor should remove them regularly.	20 Apr 2023	~	Item was rectified on 27 Apr 2023.		
Impact on Cultural Heritage					
Permits / Licenses					

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but rectified by the contractor

MA20003/App F CINOTECH