# Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

## **Appendix F - Site Audit Summary**

### February 2024

Items	Date	Status*	Follow up Action			
Water Quality						
Ecology						
Noise						
Landscape and Visual						
Air Quality						
No enclosure was observed when conducting cmenet mixing activities.	22 Feb 2024	1	Item was rectified on 29 Feb 2024.			
Waste / Chemical Management						
The rubbish was accumulated at the site entrance.	29 Feb 2024	#	To be reported in the next reporting month.			
Impact on Cultural Heritage						
Permits / Licenses						

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

\* Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

# Follow up action will be reported in next reporting month

\* Non-compliance of mitigation measure

• Non-compliance but improved by the contractor

# Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

### **Appendix F - Site Audit Summary**

### March 2024

Items	Date	Status*	Follow up Action		
Water Quality					
Noise	•	•			
Landscape and Visual	·				
Air Quality	·				
The stockpile of dusty material on the cement mixing machine was observed.	7 Mar 2024	~	Item was rectified on 14 Mar 2024.		
The NRMM label was damaged.	7 Mar 2024	$\checkmark$	Item was rectified on 14 Mar 2024.		
The NRMM label was damaged.	28 Mar 2024	#	To be reported in the next reporting month.		
Waste / Chemical Management					
The rubbish was accumulated at the site entrance	29 Feb 2024	~	Item was rectified on 7 Mar 2024.		
The chemical containers were placed on the floor without tray.	7 Mar 2024	√	Item was rectified on 14 Mar 2024.		
Impact on Cultural Heritage					
Permits / Licenses					

✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

\* Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

# Follow up action will be reported in next reporting month

\* Non-compliance of mitigation measure

• Non-compliance but rectified by the contractor

# Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

## Appendix F - Site Audit Summary

## <u>April 2024</u>

Items	Date	Status*	Follow up Action		
Water Quality					
Stagnant water should be removed to avoid mosquitoes at EVB Basement.	3 Apr 2024	✓	Item was rectified on 11 Apr 2024.		
Stagnant water should be removed to avoid mosquitoes at EVB Basement.	11 Apr 2024	✓	Item was rectified on 18 Apr 2024.		
Stagnant water should be avoided.	18 Apr 2024	$\checkmark$	Item was rectified on 25 Apr 2024.		
Noise					
Landscape and Visual					
Air Quality					
The NRMM label was damaged.	28 Mar 2024	$\checkmark$	Item was rectified on 4 Apr 2024.		
Waste / Chemical Management					
Rubbish was observed near the site entrance.	11 Apr 2024	$\checkmark$	Item was rectified on 18 Apr 2024.		
Rubbish were observed at Portion U.	25 Apr 2024	#	To be reported in the next reporting month.		
Impact on Cultural Heritage					
Permits / Licenses					

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

\* Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

# Follow up action will be reported in next reporting month

\* Non-compliance of mitigation measure

• Non-compliance but rectified by the contractor