Contract No. ED/2018/04

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Weekly Site Inspection Record Summary Inspection Information

| F • • • • • • • • • • • • • • • | |
|---------------------------------|----------------------------|
| Checklist Reference Number | 221201 |
| Date | 1 December 2022 (Thursday) |
| Time | 09:20 - 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|---|---------------------|
| | B. Water Quality | |
| 221201- R1 | • Water ponding was found near the Disc cutter workshop on the access road. | B9 |
| | C. Air Quality | |
| 221201- R2 | • Near the footbridge area, the stockpile of more than 20 bags of cement are not covered. | C20 |
| 221201- R3 | • Missing NRMM label was found in the generator near the receiving pit. | C21 |
| | D. Construction Noise Impact | |
| | • No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | • No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | • No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | • No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | • No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • Follow up on the previous session (Ref No.:221123), all item has been rectified. | |

| | Name | Signature | Date |
|-------------|-------------|-----------|-----------------|
| Recorded by | Karina Chan | Zelle | 1 December 2022 |
| Checked by | Karina Chan | Zalle | 2 December 2022 |

Contract No. ED/2018/04

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Weekly Site Inspection Record Summary Inspection Information

| Checklist Reference Number | 221208 |
|----------------------------|----------------------------|
| Date | 8 December 2022 (Thursday) |
| Time | 09:20 - 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|--|---------------------|
| | B. Water Quality | |
| | • No environmental deficiency was identified during site inspection. | |
| | C. Air Quality | |
| 221208- R2 | • Exposed stockpiles of dusty materials should be covered with impervious materials. | <i>C</i> 9 |
| | D. Construction Noise Impact | |
| | • No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| 221208- R1 | • Construction wastes are accumulated at skip ISIG in the TBM tunnels (Eastbound). | E1 |
| | F. Visual and Landscape | |
| | No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | • No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | • No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • Follow up on the previous session (Ref No.:221201), all item has been rectified. | |

| | Name | Signature | Date |
|-------------|-------------|-----------|-----------------|
| Recorded by | Karina Chan | Julle | 8 December 2022 |
| Checked by | Karina Chan | Julle | 8 December 2022 |

Contract No. ED/2018/04 Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Weekly Site Inspection Record Summary

| Inspection Information | | |
|----------------------------|-----------------------------|--|
| Checklist Reference Number | 221215 | |
| Date | 15 December 2022 (Thursday) | |
| Time | 09:20 – 12:00 | |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|--|---------------------|
| | B. Water Quality | |
| 221215- R1 | • Stagnant water was observed at the Launching Shaft Area. | B9 |
| 221215- R2 | • Muddy Water was observed at the TBM Tunnel (Eastbound). | B13 |
| | C. Air Quality | |
| | • No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | • No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | • No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | • No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | • No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | • No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • Follow up on the previous session (Ref No.:221208), all item has been rectified. | |

| | Name | Signature | Date |
|-------------|-------------|-----------|------------------|
| Recorded by | Alex NG | Alex NG | 15 December 2022 |
| Checked by | Karina Chan | Jull | 15 December 2022 |

Contract No. ED/2018/04 Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Weekly Site Inspection Record Summary

| Inspection Information | | |
|----------------------------|-----------------------------|--|
| Checklist Reference Number | 221222 | |
| Date | 22 December 2022 (Thursday) | |
| Time | 09:20 - 12:00 | |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No |
|----------|--|--------------------|
| | B. Water Quality | |
| | • No environmental deficiency was identified during site inspection. | |
| | C. Air Quality | |
| | • No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | • No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | • No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | • No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | • No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | • No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • Follow up on the previous session (Ref No.:221215), all item has been rectified. | |

| | Name | Signature | Date |
|-------------|-------------|-----------|------------------|
| Recorded by | Alex NG | Alex NG | 22 December 2022 |
| Checked by | Karina Chan | Jelle | 23 December 2022 |

Contract No. ED/2018/04 Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Weekly Site Inspection Record Summary Inspection Information

| Checklist Reference Number | 221229 |
|----------------------------|-----------------------------|
| Date | 29 December 2022 (Thursday) |
| Time | 09:20 – 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|--|---------------------|
| | <i>B. Water Quality</i>No environmental deficiency was identified during site inspection. | |
| | <i>C. Air Quality</i>No environmental deficiency was identified during site inspection. | |
| | <i>D. Construction Noise Impact</i>No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | E9 |
| 221229- R1 | • No drip tray is provided for the chemical container. | |
| | <i>F. Visual and Landscape</i>No environmental deficiency was identified during site inspection. | |
| | <i>G. Permits/Licences</i>No environmental deficiency was identified during site inspection. | |
| | <i>H. Marine Ecology</i>No environmental deficiency was identified during site inspection. | |
| | <i>I. Others</i>Follow up on the previous session (Ref No.:221222), all item has been rectified. | |

| | Name | Signature | Date |
|-------------|-------------|-----------|------------------|
| Recorded by | Alex NG | Alex NG | 29 December 2022 |
| Checked by | Karina Chan | Zelle | 30 December 2022 |

Contract No. ED/2020/03 Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works

Site Inspection Record Summary Inspection Information

| Checklist Reference Number | 221216 |
|----------------------------|---------------------------|
| Date | 16 December 2022 (Friday) |
| Time | 09:30 - 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No |
|----------|---|--------------------|
| | B. Water Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | C. Air Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | • No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | • No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | • No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • Follow up on the previous session (Ref No.:221125), no major environmental deficiency was | |
| | identified during site inspection. | |

| | Name | Signature | Date |
|-------------|-------------|-----------|------------------|
| Recorded by | Alex Ng | Alex NG | 16 December 2022 |
| Checked by | Karina Chan | Jull | 17 December 2022 |