Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230202
Date	2 February 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230126), no major environmental deficiency was	
	identified.	

	Name	Signature	Date
Recorded by	Alex NG	M	2 February 2023
Checked by	Karina Chan	Zalle	3 February 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230209
Date	9 February 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
230209- R1	• Stockpile of dusty material were observed inside the tunnel, they should be removed when not in used.	C9
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230202), no major environmental deficiency was	
	identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	9 February 2023
Checked by	Karina Chan	Zall	10 February 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230216
Date	16 February 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
230216-R1	 B. Water Quality The contractor should install the water pump to remove the water ponding in the west ventilation building. 	В9
	 C. Air Quality No environmental deficiency was identified during site inspection. 	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230209), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Als	16 February 2023
Checked by	Karina Chan	Zalle	17 February 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230223
Date	23 February 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
230223-R1	• The NRMM label display on the machinery is unclear, the contractor should replace with the new	C21
	one.	
	D. Construction Noise Impact	
	 No environmental deficiency was identified during site inspection. 	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230216), no major environmental deficiency was	
	identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	23 February 2023
Checked by	Karina Chan	Zalle	24 February 2023