Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

May 2023

Items	Date	Status*	Follow up Action
Water Quality			
Stagnant water was observed on the drip tray at the site entrance.	27 Apr 2023	✓	Item was rectified on 4 May 2023.
Ecology		-	
Noise			
Landscape and Visual			
Air Quality			
Waste / Chemical Management			
The chemical containers were not supported by drip tray.	11 May 2023	✓	Item was rectified on 18 May 2023.
The chemical containers were not supported by drip tray.	25 May 2023	#	Follow up in the next reporting month.
Impact on Cultural Heritage			
Permits / Licenses			

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

X Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

Follow up action will be reported in next reporting month

* Non-compliance of mitigation measure

• Non-compliance but improved by the contractor

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

June 2023

Items	Date	Status*	Follow up Action			
Water Quality						
Noise						
The QPME label was not valid, the contractor should replace the new label or remove them.	23 Jun 2023	~	Item was rectified on 29 Jun 2023.			
Landscape and Visual						
Air Quality						
The NRMM label was not clear.	23 Jun 2023	~	Item was rectified on 29 Jun 2023.			
Waste / Chemical Management						
The chemical containers were not supported by drip tray.	25 May 2023	~	Item was rectified on 1 Jun 2023.			
The chemical containers were not supported by drip tray.	1 Jun 2023	~	Item was rectified on 8 Jun 2023.			
General refuses (i.e plastic bottle, can) were observed inside the tunnel area.	8 Jun 2023	~	Item was rectified on 15 Jun 2023.			
The chemical containers were not supported by drip tray.	8 Jun 2023	~	Item was rectified on 15 Jun 2023.			
The chemical containers were not supported by drip tray.	29 Jun 2023	#	Follow up in the next reporting month.			
Impact on Cultural Heritage						
Permits / Licenses						

✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

* Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

Follow up action will be reported in next reporting month

* Non-compliance of mitigation measure

• Non-compliance but rectified by the contractor

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

July 2023

Items	Date	Status*	Follow up Action				
Water Quality							
Stagnant water was observed in the tray at the site entrance.	13 Jul 2023	~	Item was rectified on 20 Jul 2023.				
Noise	Noise						
Landscape and Visual							
Air Quality							
Waste / Chemical Management							
The chemical containers were not supported by drip tray.	29 Jun 2023	~	Item was rectified on 6 Jul 2023.				
Chemical label on the chemical container was damaged and should put on the drip tray to prevent chemical leakage.	20 Jul 2023	~	Item was rectified on 27 Jul 2023.				
Impact on Cultural Heritage							
Permits / Licenses							

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
Follow up action will be reported in next reporting month

* Non-compliance of mitigation measure

• Non-compliance but rectified by the contractor