

**Environmental Permit No.: EP-451/2013**  
**Environmental Team for Trunk Road T2**

**Appendix L – Summary of environmental complaint, warning, summon and notification of successful prosecution**

**Reporting Month:** August 2023

| <b>Log Ref.</b> | <b>Location</b> | <b>Received Date</b> | <b>Details of Complaint/warning/summon and prosecution</b> | <b>Investigation/Mitigation Action</b> | <b>Status</b> |
|-----------------|-----------------|----------------------|--|--|---------------|
| -               | -               | -                    | -  | -                                      | -             |

**Remarks:**

No environmental complaint/warning/summon and prosecution were received in the reporting period.

**Environmental Permit No.: EP-451/2013**  
**Environmental Team for Trunk Road T2**

**Appendix L – Summary of environmental complaint, warning, summon and notification of successful prosecution**

**Table L2 Cumulative Log for Environmental Complaint, Warning, Summon and Notification of Successful Prosecution**

| <b>Log Ref.</b> | <b>Location</b>     | <b>Received Date</b> | <b>Details of Complaint/warning/summon and prosecution</b>  | <b>Investigation/Mitigation Action</b>  | <b>Nature</b> | <b>Status</b> |
|-----------------|---------------------|----------------------|---|---|---------------|---------------|
| #A01            | The Launching Shaft | 24 June 2020         | A complaint regarding dust nuisance possible caused by the construction works at the Launching Shaft area was received. | <ul style="list-style-type: none"> <li>- Training regarding the loading and unloading height control was provided to the labourers to ensure dusty materials are transported under a minimum practical height.</li> <li>- Water sprays system was installed around the location of complaint to prevent dust generated from wind erosion on the stockpile.</li> <li>- Contractor was reminded to further enhance the dust mitigation measures to minimize the dust nuisance.</li> </ul> | Air           | Closed        |
| #N01            | The Launching Shaft | 03 & 13 July 2020    | The verbal complaint regarding the noise nuisance generated from D-wall cutter operation nearby the PWCL                | <ul style="list-style-type: none"> <li>- Noise barrier was erected between noise source and the PWCL building.</li> <li>- Construction programme was reviewed as to minimize operation of PME nearby the PWCL building</li> <li>- Contractor was recommended to implement the noise mitigation measures and other good site practices to minimize the noise nuisance.</li> </ul>  | Noise         | Closed        |

**Environmental Permit No.: EP-451/2013**  
**Environmental Team for Trunk Road T2**

**Appendix L – Summary of environmental complaint, warning, summon and notification of successful prosecution**

| Log Ref. | Location                          | Received Date    | Details of Complaint/warning/summon and prosecution  | Investigation/Mitigation Action  | Nature | Status |
|----------|-----------------------------------|------------------|--|--|--------|--------|
|          |                                   |                  | building was received by CEDD  |  |        |        |
| #N03     | The Launching Shaft               | 03 December 2020 | A verbal complaint regarding the noise nuisance, generated from the construction works nearby PWCL building, was received by CEDD. | <ul style="list-style-type: none"> <li>- Contractor has taken the remedial action (i.e. Some of the breakers in which were operated nearby the concerned area were wrapped up with the acoustic insulation sheets) and noise mitigation measures (i.e. Noise barrier was installed adjoining the building to minimize the influence of construction noise, maintenance for all Powered Mechanical Equipment was conducted regularly, review on the construction programme to minimize the operations of PME's near the PWCL) to minimize the noise impact generated from breaking activities.</li> </ul> | Noise  | Closed |
| #N10     | Launching Shaft and Barging Point | 28 February 2023 | A Complaint of Noise Nuisance caused by the nighttime construction   | <ul style="list-style-type: none"> <li>- The cause of the noise nuisance may cause by the operation of Derrick Barge and the Conveyors.</li> <li>- No limit level exceedance was recorded for additional noise monitoring and the weekly construction noise monitoring.</li> </ul>   | Noise  | Closed |

**Environmental Permit No.: EP-451/2013**  
**Environmental Team for Trunk Road T2**

**Appendix L – Summary of environmental complaint, warning, summon and notification of successful prosecution**

| Log Ref. | Location | Received Date | Details of Complaint/warning/summon and prosecution   | Investigation/Mitigation Action  | Nature | Status |
|----------|----------|---------------|---|--|--------|--------|
|          |          |               | activities was received.  | <ul style="list-style-type: none"> <li>– In addition, the Contractor shall review the construction schedule, priorities the work sequence and maintain good site practices, such as erecting noise barrier as close as possible to the noise source, replace damaged semi-enclosure/noise barrier and provide regularly maintenance for PMEs.</li> </ul>   |        |        |
|          |          | 7 March 2023  | Follow up complaint from the same complainant was received and he/she informed that the construction noise nuisance at 09:50pm. | <ul style="list-style-type: none"> <li>– The cause of the noise nuisance may cause by the operation of Derrick Barge and the Conveyors.</li> <li>– No limit level exceedance was recorded for additional noise monitoring and the weekly construction noise monitoring.</li> <li>– In addition, the Contractor shall review the construction schedule, priorities the work sequence and maintain good site practices, such as erecting noise barrier as close as possible to the noise source, replace damaged semi-enclosure/noise barrier and provide regularly maintenance for PMEs.</li> </ul> | Noise  | Closed |

**Environmental Permit No.: EP-451/2013**  
**Environmental Team for Trunk Road T2**

**Appendix L – Summary of environmental complaint, warning, summon and notification of successful prosecution**

| Log Ref. | Location                          | Received Date | Details of Complaint/warning/summon and prosecution  | Investigation/Mitigation Action   | Nature | Status |
|----------|-----------------------------------|---------------|--|---|--------|--------|
| #W01     | Launching Shaft and Barging Point | 13 March 2023 | A complaint regarding to the silt/dirt being swept into the sea from the operation of barge under Trunk Road T2. | <ul style="list-style-type: none"> <li>– There is no direct evidence that the Silt/ Dirt being swept into the sea from the barge of T2.</li> <li>– The following recommendations are made to further enhance the mitigation measures:</li> <li>– Provide regular training to site personnel on proper waste management and appropriate handling procedures.</li> <li>– Provide sufficient waste disposal points and regular collection for disposal.</li> <li>– Closely monitor the barge operation.</li> <li>– The Contractor has implemented the above environmental mitigation measures (As mentioned in Section 2.6) on site to ensure that no silt and household waste being swept into any water body.</li> </ul> | Water  | Closed |