### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230406
Date	6 April 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
230406_R3	Stagnant water was observed at the tunnel entrance.	В9
	C. Air Quality	
230406_R2	NRMM label should be enlarged for easy reference.	C21
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
230406_R1	General refuses were found near the tunnel entrance.	E1
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230330), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	6 April 2023
Checked by	Karina Chan	Zalle	7 April 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230413
Date	13 April 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230406), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	13 April 2023
Checked by	Karina Chan	Zalle	14 April 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230420
Date	20 April 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	• No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
230420-R1	Chemical wastes were observed in the tunnel area, contractor should remove them regularly.	E2
	F. Visual and Landscape	
	• No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230413), no major environmental deficiency was	
	identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	20 April 2023
Checked by	Karina Chan	Zalle	21 April 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230427
Date	27 April 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
230427-R1	Stagnant water was observed on the drip tray at the site entrance.	В9
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	• No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	• No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230420), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	27 April 2023
Checked by	Karina Chan	John	28 April 2023