Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230601
Date	1 June 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	1

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
230601- R1	Drip tray should be provided for chemical containers to prevent chemical leakage.	E9
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230525), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	M	1 June 2023
Checked by	Karina Chan	Zalle	2 June 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230608
Date	8 June 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
230608- R1	General refuses (i.e plastic bottle, can) were observed inside the tunnel area.	E1
230608_R2	Drip tray should be provided for chemical containers.	E9
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230601), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Mr	8 June 2023
Checked by	Karina Chan	Zalle	9 June 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230615
Date	15 June 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	Follow up on the previous session (Ref No.:230608), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Alr	15 June 2023
Checked by	Karina Chan	Zalle	16 June 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230623
Date	23 June 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
230623- R2	C. Air Quality The NRMM label should be replaced.	C21
230623-R1	 D. Construction Noise Impact The QPME label was not valid, the contractor should replace the new label or remove them. 	D8
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others Follow up on the previous session (Ref No.:230615), no major environmental deficiency was identified. 	

	Name	Signature	Date
Recorded by	Alex NG	M	23 June 2023
Checked by	Karina Chan	John	24 June 2023

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	230629
Date	29 June 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
230629-R1	Drip tray should be provided for chemical containers to prevent chemical leakage.	E9
	F. Visual and Landscape	
	• No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:230623), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Alex NG	Alr	29 June 2023
Checked by	Karina Chan	Zalle	30 June 2023