Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250904
Date	04 September 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
250904-EP458-R1	C. Air QualityUsed cement should be covered.	C20
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
250904-EP458-R2	 E. Waste/Chemical Management General refuse should be removed. 	E01iii
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 250828) 	

	Name	Signature	Date
Recorded by	William Yeung	K	04 Sep 2025
Checked by	Karina Chan	Zalle	08 Sep 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250910
Date	10 September 2025 (Wednesday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
	 C. Air Quality No environmental deficiency was identified during site inspection. 	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	G. Permits/LicencesNo environmental deficiency was identified during site inspection.	
	H. Marine EcologyNo environmental deficiency was identified during site inspection.	
	 I. Others Follow up on the previous session (Ref No.:250904), all the items have been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung	B	10 Sep 2025
Checked by	Karina Chan	Zalle	15 Sep 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250917
Date	17 September 2025 (Wednesday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Wasta/Chamical Managament	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	3.	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• No environmental deficiency was identified in previous session (Ref No.: 250910).	1

	Name	Signature	Date
Recorded by	William Yeung	B	17 Sep 2025
Checked by	Karina Chan	Zalle	19 Sep 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250925
Date	25 September 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	ı

Ref. No.	Remarks/Observations	Related Item No.
	 B. Water Quality No environmental deficiency was identified during site inspection. 	
	C. Air QualityNo environmental deficiency was identified during site inspection.	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 250917). 	

	Name	Signature	Date
Recorded by	William Yeung		25 Sep 2025
Checked by	Karina Chan	Zoll	29 Sep 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Weekly Site Inspection Record Summary Inspection Information

Checklist Reference Number	250905
Date	05 September 2025 (Friday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	G. Permits/LicencesNo environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250828), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung	K	05 Sep 2025
Checked by	Karina Chan	Zalle	08 Sep 2025

1 CINOTECH MA20003 $2509_audit_TCSS_CKL$

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	250910
Date	10 September 2025 (Wednesday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 I. Others Follow up on the previous session (Ref No.:250905), no major environmental deficiency was identified during site inspection. 	

	Name	Signature	Date
Recorded by	William Yeung	K	10 Sep 2025
Checked by	Karina Chan	Zelle	12 Sep 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Checklist Reference Number	250917
Date	17 September 2025 (Wednesday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	G. Permits/LicencesNo environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250910), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung	K	17 Sep 2025
Checked by	Karina Chan	Zalle	19 Sep 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Checklist Reference Number	250925
Date	25 September 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	G. Permits/LicencesNo environmental deficiency was identified during site inspection.	
	 I. Others Follow up on the previous session (Ref No.:250917), no major environmental deficiency was identified during site inspection. 	

	Name	Signature	Date
Recorded by	William Yeung	K	25 Sep 2025
Checked by	Karina Chan	Zalle	29 Sep 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	250903
Date	03 September 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations		
	B. Water Quality		
	No environmental deficiency was identified during site inspection.		
	C. EcologyNo environmental deficiency was identified during site inspection.		
	D. Landscape & Visual		
	No environmental deficiency was identified during site inspection.		
	E. Air Quality		
	No environmental deficiency was identified during site inspection.		
	 F. Construction Noise Impact No environmental deficiency was identified during site inspection. 		
	G. Waste / Chemical Management		
	No environmental deficiency was identified during site inspection.		
	H. Permits/ Licences		
	No environmental deficiency was identified during site inspection.		
	I. Impact on Cultural Heritage		
	No environmental deficiency was identified during site inspection.		
	J. Others		
	• Referring to the last site inspection report (Ref. no.: 250827), no major environmental deficiency was identified.		

	Name	Signature	Date
Recorded by	William Yeung	R	03 September 2025
Checked by	Karina Chan	Zelle	04 September 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250911
Date	11 September 2025 (Thursday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Ecology	
	No environmental deficiency was identified during site inspection.	
	D. Landscape & Visual	
	No environmental deficiency was identified during site inspection.	
	E. Air Quality	
	No environmental deficiency was identified during site inspection.	
	F. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	G. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	H. Permits/ Licences	
	No environmental deficiency was identified during site inspection.	
	I. Impact on Cultural Heritage	
	No environmental deficiency was identified during site inspection.	
	J. Others	
	• Referring to the last site inspection report (Ref. no.: 250903), no major environmental	
	deficiency was identified.	

	Name	Signature	Date
Recorded by	William Yeung		11 September 2025
Checked by	Karina Chan	Zelle	12 September 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250917
Date	17 September 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Ecology	
	No environmental deficiency was identified during site inspection.	
	D. Landscape & Visual	
	No environmental deficiency was identified during site inspection.	
	E. Air Quality	
	No environmental deficiency was identified during site inspection.	
	F. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	G. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	H. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	I. Impact on Cultural Heritage	
	No environmental deficiency was identified during site inspection.	
	J. Others	
	Referring to the last site inspection report (Ref. no.: 250911), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	William Yeung		17 September 2025
Checked by	Karina Chan	Zelle	18 September 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250926
Date	26 September 2025 (Friday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Related Item No.
ental
)

	Name	Signature	Date
Recorded by	William Yeung	K	26 September 2025
Checked by	Karina Chan	Zelle	29 September 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250930
Date	30 September 2025 (Tuesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. EcologyNo environmental deficiency was identified during site inspection.	
	D. Landscape & Visual	
	No environmental deficiency was identified during site inspection.	
	E. Air Quality	
250930-R1	Open stockpile should be well covered by impervious sheets to reduce dust emission.	E6
	 F. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	G. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	H. Permits/ Licences	
	No environmental deficiency was identified during site inspection.	
	I. Impact on Cultural Heritage	
	No environmental deficiency was identified during site inspection.	
	J. Others	
	• Referring to the last site inspection report (Ref. no.: 250926), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	William Yeung	B	30 September 2025
Checked by	Karina Chan	Zelle	02 October 2025