### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	231102
Date	02 November 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
231102-R2	Watering should regularly be sprayed in unpaved area.	C8
	D. Construction Noise Impact	
	• No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	• No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:231026), all the items have been rectified.	

	Name	Signature	Date
Recorded by	Eric Hung		02 November 2023
Checked by	Karina Chan	Zalle	03 November 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	231109
Date	09 November 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
231109-R3	NRMM label was destroyed.	C21
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
231109-R1	Oil leakage was observed in the tunnel area.	E8
231109-R2	Drip tray should be provided for chemical containers to prevent chemical leakage.	E9
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:231102), all the items have been rectified.	

	Name	Signature	Date
Recorded by	Eric Hung	Ali	09 November 2023
Checked by	Karina Chan	Zaller	10 November 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	231116
Date	16 November 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
231116-R1	Stagnant water was observed on the tray near the site entrance.	В9
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:231109), all the items have been rectified.	

	Name	Signature	Date
Recorded by	Eric Hung	Ali	16 November 2023
Checked by	Karina Chan	Zaller	17 November 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	231123		
Date	23 November 2023 (Thursday)		
Time	09:20 – 12:00		

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:231116), all the items have been rectified.	

	Name	Signature	Date
Recorded by	Eric Hung		23 November 2023
Checked by	Karina Chan	Zalle	24 November 2023

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	231130
Date	30 November 2023 (Thursday)
Time	09:20 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
231130-R1	Stagnant water was identified. (EVB)	В9
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
231130-R2	Noise barrier should be properly installed. (EVB)	D7
	E. Waste/Chemical Management	
231130-R3	Drip tray should be provided for chemical container to prevent leakage. (Westbound)	E9
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	No environmental deficiency was identified in previous session (Ref No.:231123).	

	Name	Signature	Date
Recorded by	Eric Hung		30 November 2023
Checked by	Karina Chan	Zalle	01 December 2023