




Note:

- 1) The major activities being carried out on site during the reporting period can be referred to Section 1.3.1.
- 2) The weather conditions during monitoring in the reporting period was range from cloudy and fine.
- 3) Any other factors which might affect the monitoing results can be referred to Section 2.3.4.
- 4) KTD2a was relocated to KTD2b on 9 August 2018
- 5)Power supply of high volume sampler at KER1b was suspended on 8 October 2018 due to the damage of the cable, TSP monitoring was resumed at 10 October 2018.



- Note:
- 1) The major activities being carried out on site during the reporting period can be referred to Section 1.3.1.
 - 2) The weather conditions during monitoring in the reporting period was ranged from cloudy and fine.
No raining or wind with speed over 5 m/s was observed during monitoring in the reporting period.
 - 3) Any other factors which might affect the monitoring results can be referred to Section 2.3.4.
 - 4) KTD2a was relocated to KTD2b on 9 August 2018