## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	220408
Date	08 April 2022 (Friday)
Time	14:00 – 15:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:220330), all item has been rectified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	08 April 2022
Checked by	Karina Chan	Zalle	08 April 2022

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	220414
Date	14 April 2022 (Thursday)
Time	09:15 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection	
	E. Waste/Chemical Management	
220414 - R1	Drip tray should be provided for chemical at Launching shaft	E9
220414 - R2	Waste should be cleared at launching shaft.	E1iii
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:220408), no major environmental deficiency was	
	identified	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	14 April 2022
Checked by	Karina Chan	Zalle	14 April 2022

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	220421
Date	21 April 2022 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
220421 - R1	Works area should be surrounded by bunds for flood protection.	B2
	C. Air Quality	
220421 – R2	Damaged NRMM label was observed	C21
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:220414), all items has been rectified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	21 April 2022
Checked by	Karina Chan	Zalle	21 April 2022

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	220428
Date	28 April 2022 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	• No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:220421), all items has been rectified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	28 April 2022
Checked by	Karina Chan	Zalle	28 April 2022