Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	241003
Date	03 October 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
	 C. Air Quality No environmental deficiency was identified during site inspection. 	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
241003-EP458-R1	 E. Waste/Chemical Management The Contractor is reminded to remove the empty chemical containers in EVB to keep the site tidy. 	E4ii
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others Follow up on the previous session (Ref No.:240926), all the items have been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung	K	03 October 2024
Checked by	Karina Chan	Zalle	04 October 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	241010
Date	10 October 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	• No environmental deficiency was identified during site hispection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:241003), all the items have been rectified.	

	Name	Signature	Date
Recorded by	William Yeung	B	10 October 2024
Checked by	Karina Chan	Zalle	11 October 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	241017
Date	17 October 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	• No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chamical Management	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marina Faalagu	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• No environmental deficiency was identified in previous session (Ref No.: 241017).	

	Name	Signature	Date
Recorded by	William Yeung	B	17 October 2024
Checked by	Karina Chan	Zalle	18 October 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	241024
Date	24 October 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	 B. Water Quality No environmental deficiency was identified during site inspection. 	
	C. Air QualityNo environmental deficiency was identified during site inspection.	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 241017). 	

	Name	Signature	Date
Recorded by	William Yeung	B	24 October 2024
Checked by	Karina Chan	Zoll	25 October 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	241031
Date	31 October 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Othore	
	I. Others	
	 No environmental deficiency was identified in previous session (Ref No.: 241024). 	

	Name	Signature	Date
Recorded by	William Yeung	B	31 October 2024
Checked by	Karina Chan	Zoll	01 November 2024