



**Weekly Site Inspection Record Summary**

**Inspection Information**

Checklist Reference Number	210204
Date	04 February 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p><b>B. Water Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>C. Air Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>D. Construction Noise Impact</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>E. Waste/Chemical Management</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>F. Visual and Landscape</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>G. Permits/Licences</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>H. Marine Ecology</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>I. Others</b></p> <ul style="list-style-type: none"><li>Follow-up on the previous session (Ref No.:210128), all item has been rectified.</li></ul>	



	Name	Signature	Date
Recorded by	Tim Lui		04 February 2021
Checked by	Karina Chan		04 February 2021

**Weekly Site Inspection Record Summary****Inspection Information**

Checklist Reference Number	210211
Date	11 February 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
210211 – R1	<b>B. Water Quality</b> • Muddy water and stillwater should be avoided after rain storm.	B9
210211 – R3	<b>C. Air Quality</b> • Stockpile of excavated material shall be covered.	C9
210211 – R2	<b>D. Construction Noise Impact</b> • No environmental deficiency was identified during site inspection.  <b>E. Waste/Chemical Management</b> • Oil Stain was observed..  <b>F. Visual and Landscape</b> • No environmental deficiency was identified during site inspection.  <b>G. Permits/Licences</b> • No environmental deficiency was identified during site inspection.  <b>H. Marine Ecology</b> • No environmental deficiency was identified during site inspection.  <b>I. Others</b> • No major environmental deficiency was identified during previous session (Ref No.:210204).	E8

	Name	Signature	Date
Recorded by	Tim Lui		11 February 2021
Checked by	Karina Chan		11 February 2021



**Weekly Site Inspection Record Summary**

**Inspection Information**

Checklist Reference Number	210218
Date	18 February 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p><b>B. Water Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>C. Air Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>D. Construction Noise Impact</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>E. Waste/Chemical Management</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>F. Visual and Landscape</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>G. Permits/Licences</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>H. Marine Ecology</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>I. Others</b></p> <ul style="list-style-type: none"><li>Follow up on the previous session (Ref No.:210211), all item has been rectified.</li></ul>	

	Name	Signature	Date
Recorded by	Tim Lui		18 February 2021
Checked by	Karina Chan		18 February 2021



**Weekly Site Inspection Record Summary**

**Inspection Information**

Checklist Reference Number	210225
Date	25 February 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p><b>B. Water Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>C. Air Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>D. Construction Noise Impact</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>E. Waste/Chemical Management</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>F. Visual and Landscape</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>G. Permits/Licences</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>H. Marine Ecology</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>I. Others</b></p> <ul style="list-style-type: none"><li>No major environmental deficiency was identified on the previous session (Ref No.:210218).</li></ul>	

	Name	Signature	Date
Recorded by	Tim Lui		25 February 2021
Checked by	Karina Chan		25 February 2021