

AM4 - Sitting-out Area at Cha Kwo Ling Village AM4 - Sitting-out Area at Cha Kwo Ling Village Figure 100 AM4 - Sitting-out Area at Cha Kwo Ling Village Figure 100 Figure

Notes:

- 1. The major activitie(s) being carried out on site during the reporting period is/are presented in Section 1.10
- 2. The weather conditions during the reporting month are presented in Section 3.1.
- 3. Other factors which might affect the monitoring results are presented in Section 3.16.

Contract No. ED/2018/04
Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron


Graphical Presentation of 1-hour TSP Monitoring Results


Scale
N.T.S
No. MA20003

TNOTECH

Oct-22

C





Notes:

- 1) The major activitie(s) being carried out on site during the reporting period is/are presented in Section 1.10
- 2) The weather conditions during the reporting month are presented in Section 3.1.
- 3) Other factors which might affect the monitoring results are presented in Section 3.16.

Contract No. ED/2018/04
Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron
Graphical Presentation of 24-hour TSP Monitoring Results

Scale
N.T.S
No. MA20003
Date
Oct-22
Appendix
C