



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251002
Date	02 October 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
251002-EP458-R1	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> Drip tray should be provided to oil drum or chemical. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 250925) 	E9

	Name	Signature	Date
Recorded by	William Yeung		02 Oct 2025
Checked by	Karina Chan		06 Oct 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251009
Date	09 October 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> Follow up on the previous session (Ref No.:251002), all the items have been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung		09 Oct 2025
Checked by	Karina Chan		13 Oct 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251016
Date	16 October 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251009). 	

	Name	Signature	Date
Recorded by	William Yeung		16 Oct 2025
Checked by	Karina Chan		20 Oct 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251023
Date	23 October 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251016). 	

	Name	Signature	Date
Recorded by	William Yeung		23 Oct 2025
Checked by	Karina Chan		27 Oct 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251030
Date	30 October 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251023). 	

	Name	Signature	Date
Recorded by	William Yeung		30 Oct 2025
Checked by	Karina Chan		03 Nov 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251002
Date	02 October 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:250925), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		02 Oct 2025
Checked by	Karina Chan		06 Oct 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251009
Date	09 October 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251002), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		09 Oct 2025
Checked by	Karina Chan		13 Oct 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251017
Date	17 October 2025 (Friday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">• Follow up on the previous session (Ref No.:251009), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		17 Oct 2025
Checked by	Karina Chan		20 Oct 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251023
Date	23 October 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251017), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		23 Oct 2025
Checked by	Karina Chan		27 Oct 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251030
Date	30 October 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251023), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		30 Oct 2025
Checked by	Karina Chan		03 Nov 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251008
Date	08 October 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Follow up on previous audit session (Ref No.:250930), all recorded items had been rectified. 	



	Name	Signature	Date
Recorded by	William Yeung		08 October 2025
Checked by	Karina Chan		09 October 2025

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	251015
Date	15 October 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251008), no major environmental deficiency was identified. 	



	Name	Signature	Date
Recorded by	William Yeung		15 October 2025
Checked by	Karina Chan		16 October 2025

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	251022
Date	22 October 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
251022-R1	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> General refuse (i.e. water bottles) was found inside drainage channel. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251015), no major environmental deficiency was identified. 	G1iii



	Name	Signature	Date
Recorded by	William Yeung		22 October 2025
Checked by	Karina Chan		23 October 2025

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	251030
Date	30 October 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Follow up on previous audit session (Ref No.:251022), all recorded items had been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung		30 October 2025
Checked by	Karina Chan		31 October 2025