



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251106
Date	06 November 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251030) 	

	Name	Signature	Date
Recorded by	William Yeung		06 Nov 2025
Checked by	Karina Chan		10 Nov 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251113
Date	13 November 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251106) 	

	Name	Signature	Date
Recorded by	William Yeung		13 Nov 2025
Checked by	Karina Chan		17 Nov 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251120
Date	20 November 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251113) 	

	Name	Signature	Date
Recorded by	William Yeung		20 Nov 2025
Checked by	Karina Chan		24 Nov 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251127
Date	27 November 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251120) 	

	Name	Signature	Date
Recorded by	William Yeung		27 Nov 2025
Checked by	Karina Chan		01 Dec 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251106
Date	06 November 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251030), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		06 Nov 2025
Checked by	Karina Chan		10 Nov 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251114
Date	14 November 2025 (Friday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251106), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		14 Nov 2025
Checked by	Karina Chan		17 Nov 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251120
Date	20 November 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">• No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">• Follow up on the previous session (Ref No.:251114), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		20 Nov 2025
Checked by	Karina Chan		24 Nov 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251127
Date	27 November 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251120), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		27 Nov 2025
Checked by	Karina Chan		01 Dec 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251105
Date	05 November 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251030), no major environmental deficiency was identified. 	

	Name	Signature	Date
Recorded by	William Yeung		05 November 2025
Checked by	Karina Chan		06 November 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251112
Date	12 November 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251105), no major environmental deficiency was identified. 	

	Name	Signature	Date
Recorded by	William Yeung		12 November 2025
Checked by	Karina Chan		13 November 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251121
Date	21 November 2025 (Friday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
251121-R1	<p>B. Water Quality</p> <ul style="list-style-type: none"> The Contractor is reminded to maintain the drainage (i.e. avoid stacking material inside the channel). <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251112), no major environmental deficiency was identified. 	B7

	Name	Signature	Date
Recorded by	William Yeung		21 November 2025
Checked by	Karina Chan		24 November 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251126
Date	26 November 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Follow up on previous audit session (Ref No.:251121), all recorded items had been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung		26 November 2025
Checked by	Karina Chan		27 November 2025