



**Weekly Site Inspection Record Summary
Inspection Information**

Checklist Reference Number	251204
Date	04 December 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
251204-EP458-R1 251204-EP458-R2	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> NRMM Label should be provided to PME. Cement bags should be covered with a top if more than 20 bags per stack. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251127). 	C21 C20

	Name	Signature	Date
Recorded by	William Yeung		04 Dec 2025
Checked by	Karina Chan		08 Dec 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251211
Date	11 December 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> Follow up on the previous session (Ref No.:251204), all the items have been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung		11 Dec 2025
Checked by	Karina Chan		15 Dec 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251218
Date	18 December 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251211). 	

	Name	Signature	Date
Recorded by	William Yeung		18 Dec 2025
Checked by	Karina Chan		22 Dec 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251224
Date	24 December 2025 (Wednesday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> No environmental deficiency was identified in previous session (Ref No.: 251218). 	

	Name	Signature	Date
Recorded by	William Yeung		24 Dec 2025
Checked by	Karina Chan		29 Dec 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251204
Date	04 December 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251127), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		04 Dec 2025
Checked by	Karina Chan		08 Dec 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251212
Date	12 December 2025 (Friday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251204), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		12 Dec 2025
Checked by	Karina Chan		15 Dec 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251218
Date	18 December 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251212), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		18 Dec 2025
Checked by	Karina Chan		22 Dec 2025

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251224
Date	24 December 2025 (Wednesday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:251218), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		24 Dec 2025
Checked by	Karina Chan		29 Dec 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251203
Date	03 December 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251126), no major environmental deficiency was identified. 	



	Name	Signature	Date
Recorded by	William Yeung		03 December 2025
Checked by	Karina Chan		04 December 2025

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	251210
Date	10 December 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251203), no major environmental deficiency was identified. 	



	Name	Signature	Date
Recorded by	William Yeung		10 December 2025
Checked by	Karina Chan		11 December 2025

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	251218
Date	18 December 2025 (Thursday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
251218-R1	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> Oil stains were observed on ground. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251210), no major environmental deficiency was identified. 	G9

	Name	Signature	Date
Recorded by	William Yeung		18 December 2025
Checked by	Karina Chan		19 December 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251224
Date	24 December 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Follow up on previous audit session (Ref No.:251218), all recorded items had been rectified. 	

	Name	Signature	Date
Recorded by	William Yeung		24 December 2025
Checked by	Karina Chan		29 December 2025



Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	251231
Date	31 December 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Landscape & Visual</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Waste / Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Permits/ Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Impact on Cultural Heritage</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>J. Others</p> <ul style="list-style-type: none"> Referring to the last site inspection report (Ref. no.: 251224), no major environmental deficiency was identified. 	

	Name	Signature	Date
Recorded by	William Yeung		31 December 2025
Checked by	Karina Chan		02 January 2026